UNIVERSITY OF TOLEDO

SUBJECT: RADIATION EXPOSURES FROM NON-UNIVERSITY FACILITIES

PROCEDURE STATEMENT

Employees must report to the Radiation Safety Officer any radiation exposures received from a non-University facility

PURPOSE OF PROCEDURE

To ensure the total exposure (University of Toledo and outside) to that person does not exceed the Ohio Department of Health Total Effective Dose Equivalent.

PROCEDURE

- 1. It is the responsibility of employees who are employed elsewhere and are subjected to radiation exposure from radioactive materials or radiation generating equipment to report this to the Radiation Safety Officer (RSO) at 419-383-4301.
- 2. The attached form should be used to accomplish this.
- 3. This information **must** be reported on a quarterly basis at **least**.
- 4. It will be the responsibility of the RSO to monitor the combined/total dose and inform the employee of any level exceeding the regulated permissible dose.

Source: Radiation Safety Office Effective Date: 1/1/94

Review/Revision Date: 3/21/95

Procedure No: HM-08-014

1/27/99 7/17/02

6/20/96

2/22/05 2/7/08 2/3/11 12/10/13

09/29/16 09/27/19

09/27/22

RADIATION EXPOSURES RECEIVED FROM NON-UNIVERSITY FACILITIES

ame:
ocial Security No.:
niversity Participant No. (5 digit badge no.):
ame of non-University facility:
ept. at facility:
ontact person at facility:
ate of hire:
xpected duration of employment:
tatus (student, volunteer, employee):
ype of radiation exposure (x-ray, gamma):
ype of monitoring (film badge, TLD, dosimeter):
requency of monitoring (weekly, monthly, quarterly):