


**UNIVERSITY OF TOLEDO
FACILITIES AND CONSTRUCTION**

| | | | |
|----------------------------|---|--------------------------|----------------------|
| Section: | Central Control | Procedure Number: | CC-17 |
| Subject: | Hospital TB Room Fan Failure | Effective Date: | August 1998 |
| | | Revised Date: | October 2016 |
| Facilities Officer: |  | Reviewed Date: | February 2023 |

Standard Operating Procedure

Specific protocols must be implemented immediately in the event that the TB Isolation fan fails.

Purpose

To insure timely response and to limit contamination.

Procedure

Upon receiving alarm of TB fan failure, immediately contact the following areas and individuals:

1. Nursing Supervisor on call through operator.
2. Ann Keegan, Office 383-5006
3. Heather Lorenz, Cell 419-206-0896, Office 530-3603
4. See attached chart