Name of Policy:	Lost radiation monitor			
Policy Number:	3364-135-109	THE UNIVERSITY OF TOLEDO MEDICAL CENTER		
Department:	Radiology	WEDICAL GENTER		
Approving Officer:	Chief Operating Officer - UTMC			
Responsible Agent:	Chairman & Professor, Radiology	Effective Date: 6/1/2023		
Scope:	Radiology	Initial Effective Date: 6/14/2000		
New policy proposal Minor/technical revision of existing policy Major revision of existing policy X Reaffirmation of existing policy				

(A) Policy Statement

Lost Radiation Monitors must be reported to the Radiation Safety Office.

(B) Purpose of Policy

To ensure continuity of recording of personal radiation exposure.

(C) Procedure

- 1. Any lost personal radiation monitor must be reported to the Radiation Safety Office immediately.
- 2. A replacement badge will be issued by the Radiation Safety Office.
- 3. Monitors lost greater than 30 days will be averaged over the last three months to assess an approximate radiation exposure.
- 4. Any unusual events that may have occurred while wearing the lost monitor will be reported to the Radiation Safety Officer.

Approved by:		Review/Revision Date:
		9/1/2005
		5/28/2008
/ _S /		5/20/2011
Haitham Elsamaloty, MD	Date	6/3/2014
Chairman & Professor, Radiology	6/1/2017	
, C.		6/1/2020
		6/1/2023
/s/		
Ryan Landis, BSRT, (R) (CT)	Date	
Director, Radiology		
Review/Revision Completed By:		
Haitham Elsamaloty, MD		Next Review Date: 6/1/2026
Policies Superseded by This Policy: R-025		